

**TO BE FILLED BY THE INSPECTING OFFICER**

(ASSISTANT ENGINEER)

THULASI. K

PEN.No: 451736

1. Name of Officer : Assistant Engineer  
S&D Section, Mannur GP
2. Name of school : Mominseena public school  
Mannur
3. Location / with name of Education District / Sub District : Mannur - Ottappalam (sub)
4. Classification of Building and size : RCC Bwlding (GF+FF+SF)
5. Period of which the certificate issued : 2022-23
6. Nature of defects if any
- a) Foundation & Basement
  - b) Super structure
  - c) Doors & Windows
  - d) Wood work wroughts put up
  - e) Roof
  - f) Flooring
  - g) Miscellaneous (cracks etc)
7. Any major defects noticed which will render the building unsafe in any manner : No
8. Whether maintenance works have been done Properly : Yes
9. Whether the structure is sound on for conducting classes : Yes
- Class room - 28 nos  
Lab - 5 nos  
Office - 1 no  
Library - 1 no  
Staff - 3 nos  
Sports - 1 no  
Principal room - 1 no  
40 nos.

- Note:-
1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure to flood etc.
  2. Any additional observations if deemed necessary for the certificate may be furnished separately with the certificate.

Certified that the school was inspected by me on 25/5/2022

and found to be fit/unfit to conduct classes

for the period 2022-23.  
for the reasons noted above.

Place

Date



Signature

THULASI. K

PEN.No: 451736

Assistant Engineer

S&D Section, Mannur GP